

TROUBLESHOOTING ASSISTANCE

Crane Care™ **CCS DISPLAY UPDATE** TA20-218-A Product Improvement Program (PIP): Service bulletin: Welding instructions: Crane family: GME Range: MD/MDT Model:CCS Α **Technical Support** 10/02/2020 Creation Written by Date Comment Index **DIAGNOSIS** CCS update with USB STICK Display Programming The usb key must contain the file necessary for programming the screen if it has a version prior to V2.6.2: ccs5121 - Insert the usb stick. Hold the 4 corners and OK keys for 5 seconds to reboot it. When screen turns black hold the 2 top corners keys only - Continue to hold the keys for about 15 secondes until the black screen appear and release the keys. **SOLUTION** Manitow








- The display reboot in USB stick, when the programming screen appear press OK to start flashing.







Then the screen restarts the programming is done